

CRUISING ALMANAC 2021

CUMULATIVE CORRECTIONS ISSUE 11.0

Cut-off date 30 June 2021

The Cruising Association, its officers, members, the editor and individual authors make no warranty as to the accuracy or reliability of any information contained in this publication and accept no liability for any loss, injury or damage occasioned to any person acting or refraining from action as a result of the use of such information or any decision made or action taken in reliance or partial reliance on it save that nothing contained in this publication in any way limits or excludes liability for negligence causing death or personal injury or for anything which may not legally be excluded or limited. No national hydrographic office has verified the information in these corrections and none accept liability for the accuracy of reproduction or any modifications made thereafter therefore **this product should not be used for navigation**. New or amended Notices since the last Issue will be highlighted thus.

Please report any errors or omissions to almanac@theca.org.uk.

Covid-19

The Covid-19 crisis has prohibited or restricted cruising in many countries. For the latest information please visit:

https://www.theca.org.uk/public/covid_19_cruising_restrictions

General Information

pp13 & 14 **BREXIT, EFFECTS OF BREXIT, CUSTOMS and PETS FROM ABROAD**
Replace these paragraphs by new May text **CUSTOMS AND IMMIGRATION** for which [click here](#).

Delete the Link in the Corrections Issue 9.0 *Ed*

p16 **FIRST AID** Col 2, final sentence. Delete "This is available as a free download." and substitute "This may be purchased as a hardback or downloadable pdf." *Ed*

p18 **DENMARK**
Danmarks Radio 243kHz: Insert Additional time 1143 *RE*

p19 **FRANCE**
Amend last box to read
Anse de l'Aiguillon Chassiron 63 Every 20 mins
to the Spanish Frontier Cap-Ferret 63 Every 20 mins
(Etel)

p19 **SPAIN**
Amend first table to read

Station	VHF	Times
Bilbao	10, 74	0433 0833 1033 2233
Santander	72	0500, 1100, 1500, 2100
Gijón	10	0900 2100
A Coruña	10	0005, 0405, 0805, 1605, 2005
Finisterre	11	4-hourly from 0233
Vigo	10	4-hourly from 0015
Cádiz	15	4-hourly from 0315
Tarifa	10	Even hours +0015
Huelva	10	0815, 1215, 2015
Algeciras	74	0515, 1515, 2315

p19 **SPAIN**
Amend final line of second table to read
Tarifa 83 0200, 1115, 1633

England South Coast

p27 **ISLES OF SCILLY St Mary's**
Insert unlit Special buoy in 49° 54'·70N., 6° 18'·90W.
NM2131/21

p34 **FALMOUTH, Plan**
Insert legend, **ENTRY RESTRICTED** centered on: 50° 09'·327N., 5° 03'·134W
NM93/21

p48 **RIVER EXE, Plan**
Insert E card buoy *Q(3)10s* 50° 36'·87N., 3° 26'·51W.
NM1128/21

Move buoys No4 No5 and No6 to the following positions:
No.4 Red buoy 50° 36.186N, 3° 23.996W.
No.5 Green buoy 50° 36.306N, 3° 23.958W.
No.6 Red buoy 50° 36.291N, 3° 24.024W. Exeter *NM12/21*

p 50 **PORTLAND HARBOUR, Plan**
Delete Tr in 50° 36'·65N 2° 26'·78W and associated
(R Lts) *RE*

p50 **WEYMOUTH HARBOUR, Plan**
Delete Tr in 50° 36'·65N 2° 26'·78W and associated legend
'Sealife Tr (53) R lts'. *RE*

p50 **WEYMOUTH, Text**
Approach. Delete 'From at the top' *RE*

p53 **STUDLAND BAY AND POOLE APPROACHES,**
Plan:
Delete lit S card buoy **South Hook** in 50° 39'·61N.,
1° 55'·20W. *NM1308/21*
[Click here](#) for updated plan. *Imray*

p53 **POOLE HARBOUR**, Test

Approach Delete “ From the E, . . . rise of tide. “

Insert “ From the E, pass between the G buoy *Bar Buoy* No1 and R buoy No2. Beware of past moving commercial traffic.

Entrance, colt 4 line 9 Amend “ Outer end . . . EL2 buoys.” to “ East side of Hook Sand is marked by R buoys EL2 and EL4”

p56 **CHRISTCHURCH**, Text

Tel Harbour Authority: **Amend** “Christchurch . . . 486 321” to “Bournemouth Christchurch and Poole Council. Tel 01202 123800”

Insert “ VHF 8 Marine Patrol Service: *Mike Pappa* ” Ed

p56 **NEEDLES CHANNEL**, Plan

Insert depth, 0.6, enclosed by 2m contour, and extend 5m contour W to enclose in 50° 41′.81N., 1° 35′.63W.

NM2055/21

p63 **SOUTHAMPTON WATER**, Plan

Insert AIS, at chimney in 50° 49′.06N., 1° 19′.75W.

NM1394/21

p69 **LANGSTONE HARBOUR**, Plan

Move R buoy *VQ.R*, from: 50° 48′.75N., 1° 01′.84W. to: 50° 48′.69N., 1° 01′.82W.

Move R buoy *FL.R.4s*, from: 50° 49′.09N., 1° 02′.12W.

to: 50° 48′.99N., 1° 02′.07W.

Delete unlit bn in 50° 48′.21N., 1° 01′.86W. NM331/21

p72 **CHICHESTER HARBOUR (EAST)**, Plan

Move unlit G buoy from: 50° 47′.42N., 0° 54′.70W.

to: 50° 47′.43N., 0° 54′.65W

NM6291/20

p73 **LITTLEHAMPTON** Plan

Insert Light Q.R in 50° 48′.448N., 0° 32′.784W

NM5909/20

p74 **BRIGHTON**, Plan

Delete R can buoy *Fl(5)R.10s* in 50° 48′.59N., 0° 06′.45W.

NM191/21

p76 **DOVER**, Text

In first bulleted paragraph amend “late 2021” to “spring 2022”.

Entrance at end of second paragraph, insert:-

“Visitors must contact the marina office before their planned trip to ensure entry on 01304 241 663 or email marina@doverport.co.uk.”

Amend the **Berthing** paragraph to:-

Berthing in Granville Dock through gate open HW -0350 to +0450.

Tidal harbour access 24/7 but very limited berthing.

To enter these, pass south of the Prince of Wales pier and when instructed enter the **one-way** Wick Channel. Keep in this channel until Ldg Lt F 324°-333° opens, especially near LW.

If instructed to enter the Wellington dock, which may be suitable for a long stay, pass through the new marina to the lock gate and road bridge. At the time of writing opening times had not been fixed.

Amend the **Anchoring** paragraph to:

Anchoring no longer permitted, unless instructed by the Harbour Master.

p77 **DOVER HARBOUR**, Plan

Amend light to, *VQ.14m4M* in 51° 06′.85N., 1° 19′.38E

NM5197/20

Insert light *2F.R(vert)* on ESE end of marina pier in

51° 07′.093N., 1° 19′.239E.

NM622/21

p83 **THAMES ESTUARY PASSAGE**, Plan

Insert R can buoy *FL.R.5s* in 51° 24′.58N., 1° 26′.12E.

NM800/21

Amend fog signal on **S Knock** light buoy to, *Bell*, in

51° 34′.14N., 1° 34′.29E.

NM2229/21

England East Coast

p92 **RIVERS CROUCH AND ROACH**, Plan

Delete Lit G buoy, **Fairway No 3** in 51° 37′.18N.,

0° 49′.91E

NM4735/20

Move unlit Y buoy **Raysand**, from: 51° 39′.10N.,

0° 59′.50E. to 51° 39′.08N., 0° 59′.28E.

NM4836/20

Delete R can buoy **Fairway No 2** in 51° 37′.27N.,

0° 48′.84E.

NM2655/21

p100 **RIVER DEBEN**, Plan

Amend positions of entrance buoys as follows:

West Knoll 51° 58′.415N 001° 22′.997E

Knoll Spit 51° 58′.509N 001° 23′.141E

Mid Knoll 51° 58′.549N 001° 23′.199E

TH March 21

p100 **RIVER DEBEN**, Text

Amend second website to www.debenestuarypilot.co.uk

RE May 21

p101 **RIVERS ORE AND ALDE**, Plan

Delete **Orfordness Lighthouse** and legend in 52°05′.00N

1°34.40E.

Editor 2/2021

Bar Buoys Following a Trinity House survey in March

2021, move seasonal buoys as follows:

Oxley to 52°02′.024N 01°27′.964E

Weir to 52°02′.260N 01°27′.560E

TH March 21

p105 **BLAKENEY HARBOUR**, Plan

Insert

No 3A Stb buoy *Fl.G 1s* in 52°58′.94., 0° 58′.15E

Amend as follows

No 1 Port buoy *Fl.R.* in 52° 58′.94 N, 0° 58′.15E

No 2 Stb buoy *Fl..G.5s* in 52° 58′.87N., 0° 58′.00E

No 3 Stb buoy *Fl.G.4s* in 52° 58′.98N., 0° 58′.03 E

No 4 Stb buoy *Fl G 2.5s* in 52° 58′.78N, 0° 57′.53E

Local 25/11/20

Col 2 last 4 lines to top of Col 3: Amend “Charlie Ward ...

... pilot boat)” to “Blakeney Harbour Association as

follows: Henry Archer 07786092405 or Neil Thompson

07929181138 or Will Darby 07795463943.”

Entrance Amend first two lines to “ In May 2021 the channel was very close to”

Blakeney Hbr

p106 **WELLS-NEXT-THE-SEA**

Move W card **Wells Harbour** Q(9)15s to: 52° 59′.68N.,

0° 50′.24E.

NM3218/20

p109 **RIVER HUMBER ENTRANCE**, Plan

Replace **BYB** light float *VQ(3)5s Hawke* with **GRG** light

float *Fl(2+1)G.6s Hawke* in 53° 34′.55N., 0° 05′.54E.

NM1695/21

p116 **NORTH SUNDERLAND**, Text
Amend Mobile Tel No 0790 4726121 . *HM*

Scotland East and North Coasts

p122 **ANSTRUTHER**, Text
Telephone Amend to, HM 03451 555555 Ext 461541 *HM*

Scotland West Coast

p146 **KYLE AKIN**, Plan
Move lit R buoy Fl.R.6s, from:
57° 16'·71N., 5° 45'·31W. to: 57° 16'·68N., 5° 45'·20W.
NM4605/20

p150 **CORPACH**, Plan
Insert legend *Marine under construction* between
56° 50'·535N., 5° 07'·462W. and 56° 50'·540N.,
5° 07'·627W.
NM3768/20
Delete lit G buoy Fl.G.3s in 56° 49'·228N., 5° 07'·143W.
NM665/21

p151 **CORPACH**, Text
Delete previous notice.
Insert at end of Col 1:
The new Corpach Marina has 45 berths just W of canal
entrance. www.corpachmarina.co.uk *REMay2021*

p155 **GIGHA**, Plan
Insert Card E buoy *Q(3)10s* in 55° 40'·73N., 5° 43'·32W.
NM2545/21

p155 **PORT ELLEN**, Plan
Delete shore light Fl.G.5s in 55° 37'·65N., 6° 11'·29W.
NM1429/21

England West Coast, Wales, & Isle of Man

p175 **LIVERPOOL, RIVER MERSEY**, Plan
Amend light to, 2F.G Bell(4) 15s 53° 23'·76N.,
3° 00'·49W. *NM1044/21*

p177 **MENAI STRAIT NE ENTRANCE**, Plan
Amend Characteristics of *Trwyn Du* light in 53° 18'·77N.,
4° 02'·45W to Fl.5s19m9M Horn(1)30s. *NM4948/20*

p178 **MENAI STRAIT SW ENTRANCE**, Plan
Move G buoy *Fl.G.5s C1*, from 53° 07'·21N., 4° 24'·49W.
to 53° 07'·04N., 4° 24'·42W.
Move R buoy *Fl.R.10s C2*, from 53° 07'·30N., 4° 24'·51W.
to 53° 07'·14N., 4° 24'·36W.
Move G buoy *Q.G C3*, from 53° 07'·20N., 4° 24'·01W.
to 53° 07'·25N., 4° 23'·87W. *NM1370/21*

p181 **BARMOUTH**, Plan
Move RW buoy *LFl.10s Barmouth Outer* to: 52° 42'·81N.,
4° 04'·89W. *NM133/21*

p189 **SAUNDERSFOOT**, Plan
Replace unlit R buoy with lit Y can buoy Q.Y. in
51° 42'·48N., 4° 41'·38W. *NM5224/20*

p191 **CARDIFF AND PENARTH**
Delete shore light *DirLFl.WRG.5s* in 51° 26'·66N.,
3° 09'·93W. *NM2465/21*

p192 **PORTISHEAD**, Plan
Firefly Rocks: Amend depth 0·9 to 1·6 in 51° 29'·90N.,
2° 45'·49W *Bristol Dock Surv 2020*

p193 **WATCHET**, Text
Amend marina *mobile* tel no to 07394 238218 (out of hours)
Ed
Amend marina tel no 01984 631264 to 01984 322230 *HM*

p195 **PADSTOW**, Plan
Insert G buoy Fl.G.10s **Gun Point** in 50° 33'·26N.,
4° 56'·24W.
Insert R buoy Fl.R.5s **Brea Beach** in 50° 33'·04N.,
4° 56'·03W.
Move R buoy Fl(2)R.5s **Brea Spit**, from:
50° 33'·20N., 4° 56'·08W. to: 50° 33'·30N., 4° 56'·12W.
NM2963/20
Insert lit R buoy LFl.R.10s **Daymer** in 50° 33'·50N.,
4° 56'·12W.
Move lit G buoy Fl.G.5s **Doom Bar** to: 50° 33'·40N.,
4° 56'·28W. *NM5626/19*
Insert isolated danger buoy Fl(2)10s in 50° 33'·79N.,
4° 56'·14W
Delete isolated danger buoy Fl(2) in 50° 32'·50N.,
4° 55'·61W *NM4193/20*

Ireland

p198 **IRELAND NORTH & WEST COAST** and
p199 **IRELAND SOUTH WEST, SOUTH and EAST COASTS**

CG Radio and Met tables make amends as follows:

CG Radio & Met	VHF	
Valentia	62	
Shannon	64	
Clifden	03	
Belmullet	63	
Glen Head	03	
Malin Head	01,05	
Dublin	03	
Rosslare	05	
Mine Head	03	
Cork	02	
Bantry	05	<i>IRNM36/20</i>

p214 **WATERFORD HARBOUR**, Plan
Insert plan **DUNMORE EAST HARBOUR** Amend
pierhead light in 52° 08'·98N 6° 59'·37M from
Fl.R.10s 6m4M to Fl(3)R.10s 6m4M *NM5113/20*
Insert shore lt 2F.G(ver) in 52° 08'·87N., 6° 59'·48W.
NM190/21

p215 **KILMORE QUAY**, Text
Entrance Amend, line 2, depth amend depth from
0.9M to 1.9M. *Local NM32/2020*

p217 **DUN LAOGHAIRE HARBOUR**, Plan
Amend light to Fl.G.3s15m2M, in 53° 17′.87N., 6° 07′.84W.
NM746/21

p218 **DUBLIN BAY**, Plan
Amend light-buoy in 53° 19′.91N., 6° 04′.64W from
Mo(A)10s to Iso.4s .
NM4242/20

p219 **HOWTH**, Plan
Insert legend *Works in progress2020* in 53° 23′.47N
6°04′.16W
NM5653/20

p220 **CARLINGFORD LOUGH**, Plan
Amend
No 23 Lt buoy to, Fl(3)G.8s 54° 03′.88N., 6° 11′.12W.
No 20 Lt-buoy to, Fl(2)R.4s 54° 04′.72N., 6° 13′.25W.
Amend on Inset Plan
No 17 Lt-buoy to, Fl.G.4s 54° 02′.48N., 6° 08′.09W.
NM6254/20

p232 **SLIGO HARBOUR**, Plan
Delete Lt Bn, Lifeboat Beacon, Q.R in 54° 18′.26N., 8° 34′.05W
(OSI Datum).
NM334/21

Belgium

None to date

Netherlands

p256 **ENTRANCE TO THE WESTERSCHELDE**, Plan
Move G buoy Iso.G.8s **SS 7**, from:51° 25′.04N., 3° 38′.82E.
to: 51° 25′.13N., 3° 38′.61E
Insert G buoy without top mark Iso.G.4s **SS 9** in
51° 25′.10N., 3° 39′.81E.
Delete G buoy with top mark Iso.G.4s **SS 9** in
51° 24′.93N., 3° 39′.88E.
NM1597/21

p258 **ENTRANCE TO THE OOSTERSCHELDE**, Plan
Insert G buoy Iso.G.4s **R9** in) 51° 36′.06N., 3° 38′.57E.
and delete existing unlit buoy **R9** close E.
Insert G buoy with topmark Q,G **R11A** in 51° 36′.74N.,
3° 39′.29E.
Insert light Iso.R.4s on **R 12** buoy in 51° 36′.29N.,
3° 38′.28E.
Replace E card buoy VQ(3)5s **OR-R R** by G buoy with
topmark Iso.G.8s **R11** in 51° 36′.41N., 3° 38′.96E.
NM6056/20

p270 **ZEEGAT VAN TERSCHELLING**, Plan
Amend **ZS 3** light-buoy to, Q.G in 53° 19′.29N.,
4° 59′.48E.
ZS 4 light-buoy to, Q.R in 53° 19′.55N.,
4° 59′.64E.
NM1977/20

p271 **AMELAND (NES)**, Text
Insert Very popular in season. Dredged to 1.4m at CD.
Contact HM. Small supermarket nearby. VHF31. *Ed*

Approaches to the Baltic

None to date

France, North Coast, and Channel Islands

p 320 **LE HAVRE TO CHERBOURG**, *Passage lights*
Amend Pointe de Saire light to, Iso.4s10M
NM6050/20

p324 **ST-VAAST-LA-HOUGUE**, Plan
Amend Light, Pointe de Saire, in 49° 36′.38 N
1° 13′.79, to Iso W 4s 11m 10M
Lights List Wk47/20.

p331 **BEAUCETTE**, plan
Delete radar bn, Racon(P), at light in 49° 30′.83N.,
2° 29′.14W.
NM5309/20

p333 **ST HELIER HARBOUR**, Plan
Insert Light F.R. in 49° 10′.800N., 2° 06′.738W
NM1082/2020

p334 **CARTERET**, Text
Entrance Delete all of text from ‘During 2020’ to end of
paragraph, and replace by ‘Insert ‘At the inward end of the
fish quay a sill, dries 6.3m, marked with red and green piles
20m apart, maintains the depth of the inner hbr and marina
at 4m. The channel beyond is marked with red and green
piles.’
RE

p336 **ST-MALO APPROACHES**, Plan
Delete Automatic Identification System, AIS, at lights in
48° 40′.20N., 2° 04′.96W. (*Grand Jardin*)
48° 40′.27N., 1° 58′.69W. (*Rochebonne*)
48° 38′.13N., 2° 01′.30W. (*Les Bas-Sablons*)
48° 37′.57N., 2° 00′.25W. (*La Balue*)
NM5625/20
Delete AIS at Light buoy Iso 4s in 48° 41′.32N., 2° 07′.27W.
NM420/21

France, West Coast

None to date

Atlantic Spain and Portugal

p393 **AVILES**, Plan
Amend lights as follows:
Punta de la Forcada to Fl(1+2) 14.5s 23m in
43° 35′.83 N, 5° 56′.85 W
Punta del Castillo to Fl.R.5s 12m 5M in
43° 35′.73 N, 5° 56′.74 W
RE

p388 **PUERTO DE CASTRO URDIALES** /Text
Insert Ⓣ Club 942 86 15 85
RE

p388 **PUERTO DE LEQUEITIO**, Text
Insert Ⓣ 688 67 10 11
RE

p398 **PUERTO DE BILBAO**, Text
Amend to Tel Getxo 944 91 13 54
RE

p402 **RÍA DE PONTEVEDRA**, Plan
Insert G buoy *Iso.G.5s6M* in 42° 21′.81N., 8° 46′.16W.
NM1465/21

The CRUISING ALMANAC

TIDE TABLES 2021

p5 **PORTLAND** Delete existing page 5 and replace with [this file](#). This link includes additional amendments to the text.

p9 **SOUTHAMPTON** Delete existing page 9 and replace with [this file](#).

ON ALL ODD NUMBERED PAGES:

Amend the date of the end of **Summer Time**, marked by the shaded box, from **Saturday 23rd October to Saturday 30th October**.

For an example page go to [this link](#) . *Editor*
