

CRUISING ALMANAC 2021

CUMULATIVE CORRECTIONS ISSUE 14.0

Cut-off date 30th September 2021

The Cruising Association, its officers, members, the editor and individual authors make no warranty as to the accuracy or reliability of any information contained in this publication and accept no liability for any loss, injury or damage occasioned to any person acting or refraining from action as a result of the use of such information or any decision made or action taken in reliance or partial reliance on it save that nothing contained in this publication in any way limits or excludes liability for negligence causing death or personal injury or for anything which may not legally be excluded or limited. No national hydrographic office, or local harbour authority has verified the information in these corrections and none accept liability for the accuracy of reproduction or any modifications made thereafter therefore **this product should not be used for navigation.** New or amended Notices since the last Issue will be highlighted thus. Please report any errors or omissions to almanac@theca.org.uk.

Covid-19

The Covid-19 crisis has prohibited or restricted cruising in many countries. For the latest information please visit:

https://www.theca.org.uk/public/covid_19_cruising_restrictions

General Information

pp13 & 14 **BREXIT, EFFECTS OF BREXIT, CUSTOMS and PETS FROM ABROAD**
Replace these paragraphs by new May text **CUSTOMS AND IMMIGRATION** for which [click here](#).

Delete the Link in the Corrections Issue 9.0 *Ed*

p16 **FIRST AID** Col 2, final sentence. Delete "This is available as a free download." and substitute "This may be purchased as a hardback or downloadable pdf." *Ed*

p18 **DENMARK**
Danmarks Radio 243kHz: Insert Additional time 1143 *RE*

p19 **FRANCE**
Amend last box to read
Anse de l'Aiguillon Chassiron 63 Every 20 mins
to the Spanish Frontier Cap-Ferret 63 Every 20 mins
(Etel)

p19 **SPAIN**
Amend first table to read

Station	VHF	Times
Bilbao	10, 74	0433 0833 1033 2233
Santander	72	0500, 1100, 1500, 2100
Gijón	10	0900 2100
A Coruña	10	0005, 0405, 0805, 1605, 2005
Finisterre	11	4-hourly from 0233
Vigo	10	4-hourly from 0015
Cádiz	15	4-hourly from 0315
Tarifa	10	Even hours +0015
Huelva	10	0815, 1215, 2015
Algeciras	74	0515, 1515, 2315

p19 **SPAIN**
Amend final line of second table to read
Tarifa 83 0200, 1115, 1633

England South Coast

p24 **ENGLAND SOUTH COAST**, Upper Plan
Amend symbol **Channel** in 49° 54'.46N., 002° 53'.74W
from Lt Vessel to RW vert stripe buoy with R spherical
topmark. *TH12/2021*

p27 **ISLES OF SCILLY St Mary's**
Insert unlit Special buoy in 49° 54'.70N., 6° 18'.90W.
NM2131/21

p31 **ST MICHAEL'S MOUNT/ MARAZION**, Plan
Amend background colour of 2M depth to a pale colour in
50° 06'.98N, 5° 28'.98W *RE*

p34 **FALMOUTH**, Plan
Insert legend, **ENTRY RESTRICTED** centred on:
50° 09'.32N., 5° 03'.13W *NM93/21*

p37 **PLYMOUYH SOUND**, Plan
Delete legend "Bovisand Pier" in 50° 20'.3 N, 4° 50'.3 W.
RE

p38 **MILLBAY**, Plan
Insert legend, "Small Craft Anchorage in 50deg 21.77min N,
4deg 08.77W *RE*

p38 **MILLBAY**, Text
col 1: Anchorage Off W Hoe.
Delete "No longer sea bed." *RE*

p39 **HAMOAZE**, Plan
Amend "Sound Acre Pt" to "Sandacre Pt" in
50° 23'.6 N 4° 13'.5 W *RE*

p40 **Text Col 1**

Delete the five lines "Navigation charts." *RE*

p48 **RIVER EXE**, Plan

Insert E card buoy *Q(3)10s* 50° 36′.87N., 3° 26′.51W.
NM1128/21

Move buoys No4 No5 and No6 to the following positions:

No.4 R buoy 50° 36.186N, 3° 23.996W.

No.5 G buoy 50° 36.306N, 3° 23.958W.

No.6 Red buoy 50° 36.291N, 3° 24.024W. *ExeterNM12/21*

Insert G buoy named **Hinton** Fl (2) G 5s in 50° 36′.99N
3° 26′.29W. *ExeterNM19/21*

p 50 **PORTLAND HARBOUR**, Plan

Delete Tr in 50° 36′.65N 2° 26′.78W and associated (R Lts)
RE

p 50 **PORTLAND HARBOUR**, Plan

Delete legend, SS(Traffic), at light in 50° 34′.45N.,
2° 27′.25W. *NM3785/21*

p50 **WEYMOUTH HARBOUR**, Plan

Delete Tr in 50° 36′.65N 2° 26′.78W and associated legend
'Sealife Tr (53) R lts'. *RE*

p50 **WEYMOUTH**, Text

Approach. Delete 'From . . . at the top' *RE*

p53 **STUDLAND BAY AND POOLE APPROACHES**,

Plan:

Delete lit S card buoy **South Hook** in 50° 39′.61N.,
1° 55′.20W. *NM1308//21*
[Click here](#) for updated plan. *Imray*

p53 **POOLE HARBOUR**. Test

Approach Delete " From the E, . . . rise of tide. "
Insert " From the E, pass between the G buoy *Bar Buoy*
No1 and R buoy No2. Beware of past moving commercial
traffic.
Entrance, colt 4 line 9 Amend " Outer end . . .EL2 buoys."
to " East side of Hook Sand is marked by R buoys EL2 and
EL4"

p54 **POOLE TO CHICHESTER**, Passage Lights

With effect from 17th Sept 2021 amend **St Catherine's** Lt
Ho nominal range to 18nm. *TH 11/2021*

p56 **CHRISTCHURCH**, Text

Tel Harbour Authority: **Amend** "Christchurch . . . 486 321"
to "Bournemouth Christchurch and Poole Council. Tel
01202 123800"
Insert " VHF 8 Marine Patrol Service: *Mike Pappa* " *Ed*

p56 **NEEDLES CHANNEL**, Plan

Insert depth, 0.6, enclosed by 2m contour, and extend 5m
contour W to enclose in 50° 41′.81N., 1° 35′.63W.
NM2055/21

p63 **SOUTHAMPTON WATER**, Plan

Insert AIS, at chimney in 50° 49′.06N., 1° 19′.75W.
NM1394/21

p69 **LANGSTONE HARBOUR**, Plan

Move R buoy *VQ.R*, from: 50° 48′.75N., 1° 01′.84W.
to: 50° 48′.69N., 1° 01′.82W.

Move R buoy *Fl.R.4s*, from: 50° 49′.09N., 1° 02′.12W
to 50° 48′.99N., 1° 02′.07W.

Delete unlit bn in 50° 48′.21N., 1° 01′.86W. *NM331/21*

p72 **CHICHESTER HARBOUR (EAST)**, Plan

Move unlit G buoy from: 50° 47′.42N., 0° 54′.70W.
to: 50° 47′.43N., 0° 54′.65W *NM6291/20*

p73 **LITTLEHAMPTON** Plan

Insert Light *Q.R* in 50° 48′.448N., 0° 32′.784W
NM5909/20

p74 **BRIGHTON**, Plan

Delete R can buoy *Fl(5)R.10s* in 50° 48′.59N., 0° 06′.45W.
NM191/21

p76 **DOVER**, Text

In first bulleted paragraph amend "late 2021" to "spring
2022".

Entrance at end of second paragraph, insert:-

"Visitors must contact the marina office before their planned
trip to ensure entry on 01304 241 663 or email
marina@dovertport.co.uk."

Amend the **Berthing** paragraph to:-

Berthing in Granville Dock through gate open HW -0350 to
+0450.

Tidal harbour access 24/7 but very limited berthing.

To enter these, pass south of the Prince of Wales pier and
when instructed enter the **one-way** Wick Channel. Keep in
this channel until Ldg Lt F 324°-333° opens, especially near
LW.

If instructed to enter the Wellington dock, which may be
suitable for a long stay, pass though the new marina to the
lock gate and road bridge. At the time of writing opening
times had not been fixed.

Amend the **Anchoring** paragraph to:

Anchoring no longer permitted, unless instructed by the
Harbour Master.

p77 **DOVER HARBOUR**, Plan

Amend light to, *VQ.14m4M* in 51° 06′.85N., 1° 19′.38E
NM5197/20

Insert light *2F.R(vert)* on ESE end of marina pier in
51° 07′.093N., 1° 19′.239E. *NM622/21*

p77 **DOVER MARINA**, Plan

Insert symbol with legend SS(Traffic)
in 51° 07′.197N., 1° 18′.709E. *NM3934/21*

England East Coast

p83 **THAMES ESTUARY PASSAGE**, Plan

Insert R can buoy *Fl.R.5s* in 51° 24'·58N., 1° 26'·12E.

NM800/21

Amend fog signal on **S Knock** light buoy to, *Bell*, in

51° 34'·14N., 1° 34'·29E.

NM2229/21

p91 **RIVER CROUCH, COLNE, AND BLACKWATER APPROCHES**

Swallowtail 1 Y It buoy has been moved from 51° 41'·38N to 51°41'40N., 01°07'·50E, characteristics unchanged.

Delete It buoy **Swallowtail No 2** in 51°41'·18N., 1°06'30E

Swallowtail No 3 It buoy in 51°40'·84N., 1°04'·39E has been renamed **Swallowtail No 2** with new light characteristic Fl.Y.10s. Colour, shape and top mark remain unchanged.

Swallowtail No 4 It buoy in 51°40'·52N., 1°03'·487E has been renamed **Swallowtail No 3** Light characteristic Fl.

(2)Y.10s, colour, shape, and top mark remain unchanged.

p91 **RIVER CROUCH, COLNE, AND BLACKWATER APPROCHES**

Whitaker No 1 It buoy has been moved to a new position of 51°40'·53N., 1°05'·40E, shape, colour, top mark and light Fl.G.5 remain unchanged.

Whitaker No 2 It buoy has been moved to a new position of 51°40'·25N., 1°05'·40E, shape, colour, top mark and light Fl.R.5s remain unchanged.

Whitaker No 3 It buoy has been permanently withdrawn from 51°40'·42N., 1°04'·72E.

Whitaker No 4 It buoy has been permanently withdrawn from 51°40'·16N., 1°04'·91E.

Whitaker No 5 It buoy in 51°40'·04N., 01°03'·22E has been renamed **Whitaker No 3** with new light characteristic Fl.(2)G.5s, shape, colour and top mark remain unchanged.

Whitaker No 6 It buoy in 51°39'·77N., 01°03'·48E has been renamed **Whitaker No 4** with new light characteristic Fl.(2)R.5s, shape, colour and top mark remain unchanged.

Whitaker No 7 It buoy in 51°39'·54N., 1°02.00E has been renamed **Whitaker No 5** It buoy with new light characteristic Fl.(3)G.10s, shape, colour and top mark remain unchanged.

Whitaker No 8 It buoy in 51°39'·35N., 1°02'·00E has been renamed **Whitaker No 6** It buoy with new light characteristic Fl.(3)R.10s, shape, colour and top mark remain unchanged.

Local NM June 2021

Brigemarsch Marina Approach, Plan

Insert lit R bn Fl.R.5·5s in 51° 38'·43N., 0° 45'·80E. and delete existing lit R bn Fl.R.10s, close SW of the above.

NM3261/21

p92 **RIVERS CROUCH AND ROACH**, Plan

Delete Lit G buoy, **Fairway No 3** in 51° 37'·18N., 0° 49'·91E

NM4735/20

Move unlit Y buoy **Raysand**, from: 51° 39'·10N.,

0° 59'·50E. to 51° 39'·08N., 0° 59'·28E.

NM4836/20

Delete R can buoy **Fairway No 2** in 51° 37'·27N.,

0° 48'·84E.

NM2655/21

p100 **RIVER DEBEN**, Plan

Amend positions of entrance buoys as follows:

West Knoll 51° 58'·415N., 1° 22'·997E

Knoll Spit 51° 58'·509N., 1° 23'·141E

Mid Knoll 51° 58'·549N., 1° 23'·199E

TH March 21

p100 **RIVER DEBEN**, Text

Amend second website to www.debenestuarypilot.co.uk

RE May 21

p101 **RIVERS ORE AND ALDE**, Plan

Delete **Orfordness Lighthouse** and legend in 52°05'·00N

1°34.40E.

Editor 2/2021

Bar Buoys Following a Trinity House survey in March

2021, move seasonal buoys as follows:

Oxley to 52°02'·024N., 1°27'·964E

Weir to 52°02'·260N., 1°27'·560E

TH March 21

p105 **BLAKENEY HARBOUR**, Plan

Insert

No 3A Stb buoy Fl.G 1s in 52°58'·94N., 0° 58'·15E

Amend as follows

No 1 Port buoy Fl.R. in 52° 58'·94 N., 0° 58'·15E

No 2 Stb buoy Fl..G.5s in 52° 58'·87N., 0° 58'·00E

No 3 Stb buoy Fl.G.4s in 52° 58'·98N., 0° 58'·03 E

No 4 Stb buoy Fl G 2.5s in 52° 58'·78N., 0° 57'·53E

Local 25/11/20

Col 2 last 4 lines to top of Col 3: Amend “Charlie Ward ...

... pilot boat)” to “Blakeney Harbour Association as

follows: Henry Archer 07786092405 or Neil Thompson

07929181138 or Will Darby 07795463943.”

Entrance Amend first two lines to “ In May 2021 the

channel was very close to”

Blakeney Hbr

p106 **WELLS-NEXT-THE-SEA**

Move W card **Wells Harbour** Q(9)15s to: 52° 59'·68N.,

0° 50'·24E.

NM3218/20

p109 **RIVER HUMBER ENTRANCE**, Plan

Replace BYB light float *VQ(3)5s Hawke* with GRG light

float *Fl(2+1)G.6s Hawke* in 53° 34'·55N., 0° 05'·54E.

NM1695/21

p116 **NORTH SUNDERLAND**, Text

Amend Mobile Tel No 0790 4726121 .

HM

Scotland East and North Coasts

p122 **ANSTRUTHER**, Text

Telephone Amend to, HM 03451 555555 Ext 461541 *HM*

p132 **STROMNESS**, Plan

Amend light to, Fl.4s7m7M in 58° 56'·95N., 3° 17'·83W.

NM3462/21

p133 **SCAPA FLOW**, Plan

Amend light to, Fl.4s7m7M in 58° 56'·95N., 3° 17'·83W.

NM3462/21

Scotland West Coast

p146 **KYLE AKIN**, Plan

Move R Lt buoy Fl.R.6s, from:

57° 16'·71N., 5° 45'·31W. to: 57° 16'·68N., 5° 45'·20W.

NM4605/20

p151 **CORPACH**, Plan

Insert legend *Marine under construction* between

56° 50'·535N., 5° 07'·462W. and 56° 50'·540N.,

5° 07'·627W.

NM3768/20

Delete lit G buoy Fl.G.3s in 56° 49'·228N., 5° 07'·143W.

NM665/21

p151 **CORPACH**, Text

Delete previous notice.

Insert at end of Col 1:

The new Corpach Marina has 45 berths just W of canal

entrance. www.corpachmarina.co.uk

REMay2021

p155 **GIGHA**, Plan

Insert Card E buoy *Q(3)10s* in 55° 40'·73N., 5° 43'·32W.

NM2545/21

p155 **PORT ELLEN**, Plan

Delete shore light Fl.G.5s in 55° 37'·65N., 6° 11'·29W.

NM1429/21

p157 **STORNAWAY HARBOUR**, Plan

Amend light to Dir. WRG.4s23m5M in 58° 12'·00N.,

6° 23'·54W.

NM3002/2

p164 **ARDROSSAN**, Text

Col 1 Lines 19 to 22. Amend to:

•3 F.R.(vert). Hbr and Marina closed to all traffic.

Clyde Marina

p189 **SAUNDERSFOOT**, Plan

Replace unlit R buoy with lit Y can buoy Q.Y. in

51° 42'·48N., 4° 41'·38W.

NM5224/20

p191 **CARDIFF AND PENARTH**

Delete shore light DirLFl.WRG.5s in 51° 26'·66N.,

3° 09'·93W.

NM2465/21

p192 **PORTISHEAD**, Plan

Firefly Rocks: Amend depth 0.9 to 1.6 in 51° 29'·90N.,

2°45'·49W

Bristol Dock Surv 2020

p193 **WATCHET**, Text

Amend marina *mobile* tel no to 07394 238218 (out of hours)

Ed

Amend marina tel no 01984 631264 to 01984 322230 HM

p195 **PADSTOW**, Plan

Insert G buoy Fl.G.10s **Gun Point** in 50° 33'·26N.,

4° 56'·24W.

Insert R buoy Fl.R.5s **Brea Beach** in 50° 33'·04N.,

4° 56'·03W.

Move R buoy Fl(2)R.5s **Brea Spit**, from:

50° 33'·20N., 4° 56'·08W. to: 50° 33'·30N., 4° 56'·12W.

NM2963/20

Insert lit R buoy LFl.R.10s **Daymer** in 50° 33'·50N.,

4° 56'·12W.

Move lit G buoy Fl.G.5s **Doom Bar** to: 50° 33'·40N.,

4° 56'·28W.

NM5626/19

Insert isolated danger buoy Fl(2)10s in 50° 33'·79N.,

4° 56'·14W

Delete isolated danger buoy Fl(2) in 50° 32'·50N.,

4° 55'·61W

NM4193/20

Englandnd West Coast, Wales, & Isle of Man

p175 **LIVERPOOL, RIVER MERSEY**, Plan

Amend light to, 2F.G Bell(4) 15s 53° 23'·76N.,

3° 00'·49W.

NM1044/21

p177 **MENAI STRAIT NE ENTRANCE**, Plan

Amend Characteristics of **Trwyn Du** light in 53° 18'·77N.,

4° 02'·45W to Fl.5s19m9M Horn(1)30s.

NM4948/20

p178 **MENAI STRAIT SW ENTRANCE**, Plan

Move G buoy Fl.G.5s **C1**, from 53° 07'·21N., 4° 24'·49W.

to 53° 07'·04N., 4° 24'·42W.

Move R buoy Fl.R.10s **C2**, from 53° 07'·30N., 4° 24'·51W.

to 53° 07'·14N., 4° 24'·36W.

Move G buoy *Q.G C3*, from 53° 07'·20N., 4° 24'·01W.

to 53° 07'·25N., 4° 23'·87W.

NM1370/21

p181 **BARMOUTH**, Plan

Move RW buoy LFl.10s **Barmouth Outer** to: 52° 42'·81N.,

4° 04'·89W.

NM133/21

p185 **FISGUARD**, Text

Tel/VHF Old Harbour, Amend HM 01348 873389 to

HM 01834 842717. Insert at end “ assistant HM 07812

559483”

RE

Ireland

p198 **IRELAND NORTH & WEST COAST** and

p199 **IRELAND SOUTH WEST, SOUTH and EAST**

COASTS

CG Radio and Met tables make amends as follows:

CG Radio & Met VHF

Valentia 62

Shannon 64

Clifden 03

Belmullet 63

Glen Head 03

Malin Head 01,05

Dublin 03

Rosslare 05

Mine Head 03

Cork 02

Bantry 05

IRNM36/20

p214 **WATERFORD HARBOUR**, Plan

Insert plan **DUNMORE EAST HARBOUR** Amend

pierhead light in 52° 08'·98N 6° 59'·37M from

Fl.R.10s 6m4M to Fl(3)R.10s 6m4M

NM5113/20

Insert shore Lt 2F.G(vert) in 52° 08'·87N., 6° 59'·48W.

NM190/21

p215 **KILMORE QUAY**, Plan

Insert depth, 0₆, and extend 2.0m danger line SE to enclose

in 52° 09'·86N., 6° 34'·48W.

NM3790/21

p215 **KILMORE QUAY**, Text
Entrance Amend, line 2, depth amend depth from
0.9M to 1.9M. *Local NM32/2020*

p217 **DUN LAOGHAIRE HARBOUR**, Plan
Amend light to Fl.G.3s15m2M, in 53° 17′.87N., 6° 07′.84W.
NM746/21

p218 **DUBLIN BAY**, Plan
Amend light-buoy in 53° 19′.91N., 6° 04′.64W from
Mo(A)10s to Iso.4s. *NM4242/20*

p219 **HOWTH**, Plan
Insert legend *Works in progress*2020 in 53° 23′.47N.,
6° 04′.16W *NM5653/20*

p220 **CARLINGFORD LOUGH**, Plan
Amend
No 23 Lt buoy to, Fl(3)G.8s 54° 03′.88N., 6° 11′.12W.
No 20 Lt-buoy to, Fl(2)R.4s 54° 04′.72N., 6° 13′.25W.
Amend on Inset Plan
No 17 Lt-buoy to, Fl.G.4s 54° 02′.48N., 6° 08′.09W.
NM6254/20

p225 **FAIR HEAD TO BLOODY FORELAND**
Passage lights
Amend range of the following:
Altacarry Head (Rathlin East) from 26M to 18M
Rathlin West from 22M to 18M *NM2748/21*

p232 **SLIGO HARBOUR**, Plan
Delete Lt Bn, Lifeboat Beacon, Q.R in 54° 18′.26N., 8° 34′.05W
(OSI Datum). *NM334/21*

Belgium

None to date

Netherlands

p256 **ENTRANCE TO THE WESTERSCHELDE**, Plan
Move G buoy Iso.G.8s **SS 7**, from:51° 25′.04N., 3° 38′.82E.
to: 51° 25′.13N., 3° 38′.61E
Insert G buoy without top mark Iso.G.4s **SS 9** in
51° 25′.10N., 3° 39′.81E.
Delete G buoy with top mark Iso.G.4s **SS 9** in
51° 24′.93N., 3° 39′.88E. *NM1597/21*

p258 **ENTRANCE TO THE OOSTERSCHELDE**, Plan
Insert G buoy Iso.G.4s **R9** in) 51° 36′.06N., 3° 38′.57E.
and delete existing unlit buoy **R9** close E.
Insert G buoy with topmark Q.G **R11A** in 51° 36′.74N.,
3° 39′.29E.
Insert light Iso.R.4s on **R 12** buoy in 51° 36′.29N.,
3° 38′.28E.
Replace E card buoy VQ(3)5s **OR-R R** by G buoy with
topmark Iso.G.8s **R11** in 51° 36′.41N., 3° 38′.96E.
NM6056/20

p262 **APPROACHES TO THE MAAS**, Plan
Move Lt G buoy *LFl.G.5s* **Maas 1**, from 51° 59′.38N.,
4° 01′.67E. to: 51° 59′.36N., 4° 01′.90E. *NM3246/21*

p270 **ZEEGAT VAN TERSCHELLING**, Plan
Amend **ZS 3** Lt buoy to, Q.G in 53° 19′.29N., 4° 59′.48E.
ZS 4 Lt buoy to, Q.R in 53° 19′.55N., 4° 59′.64E.
NM1977/20

p271 **AMELAND (NES)**, Text
Insert Very popular in season. Dredged to 1.4m at CD.
Contact HM. Small supermarket nearby. VHF31. *Ed*

Approaches to the Baltic

None to date

France, North Coast, and Channel Islands

p312 **FRANCE NORTH COAST**, Plan
Amend symbol **Channel** in 49° 54′.46N., 002° 53′.74W
from Lt Vessel to RW vert stripe buoy with R spherical
topmark. *TH12/2021*

p320 **LE HAVRE TO CHERBOURG**, *Passage lights*
Amend Pointe de Saire light to, Iso.4s10M *NM6050/20*

p324 **ST-VAAST-LA-HOUGUE**, Plan
Amend Light, Pointe de Saire, in 49° 36′.38 N.,
1° 13′.79W, to Iso W 4s 11m 10M *Lights List Wk47/20.*

p331 **BEAUCETTE**, plan
Delete radar bn, Racon(P), at light in 49° 30′.83N.,
2° 29′.14W. *NM5309/20*

p333 **ST HELIER HARBOUR**, Plan
Insert Light F.R. in 49° 10′.800N., 2° 06′.738W
NM1082/2020

p334 **CARTERET**, Text
Entrance Delete all of text from ‘During 2020’ to end of
paragraph, and replace by ‘At the inward end of the fish
quay a sill, dries 6.3m, marked with red and green piles 20m
apart, maintains the depth of the inner hbr and marina at 4m.
The channel beyond is marked with red and green piles.’ *RE*

p335 **CARTERET**, Plan
Insert lights, Fl(3)R.12s2M in 49° 22′.59N., 1° 47′.24W.
and Fl(3)G.12s2M in 49° 22′.55N., 1° 47′.20W.
NM3743/21

p336 **ST-MALO APPROACHES**, Plan
Delete Automatic Identification System, AIS, at lights in
48° 40′.20N., 2° 04′.96W. (*Grand Jardin*)
48° 40′.27N., 1° 58′.69W. (*Rochebonne*)
48° 38′.13N., 2° 01′.30W. (*Les Bas-Sablons*)
48° 37′.57N., 2° 00′.25W. (*La Balue*) *NM5625/20*
Delete AIS at Light buoy Iso 4s in 48° 41′.32N., 2° 07′.27W.
NM420/21

p350 **ILE DE BATZ**, Plan
Delete W card buoy Notre Dame in 48° 43′.70N.,
3° 59′.07W. *NM3750/21*

France, West Coast

p361 **AUDIERNE**, Plan

Amend Pierhead light to Fl(2)R.6s in 48° 00′.99N.,
4° 32′.15W.

Coz Fornic light to, Fl.R.4s in 48° 00′.89N., 4° 32′.31W.

NM3516/21

Atlantic Spain and Portugal

p393 **AVILES**, Plan

Amend lights as follows:

Punta de la Forcada to Fl(1+2) 14.5s 23m in

43° 35′.83 N, 5° 56′.85 W

Punta del Castillo to Fl.R.5s 12m 5M in

43° 35′.73 N, 5° 56′.74 W

RE

p388 **PUERTO DE CASTRO URDIALES** /Text

Insert ☉ Club 942 86 15 85

RE

p388 **PUERTO DE LEQUEITIO**, Text

Insert ☉ 688 67 10 11

RE

p398 **PUERTO DE BILBAO**, Text

Amend to Tel Getxo 944 91 13 54

RE

p402 **RÍA DE PONTEVEDRA**, Plan

Insert G buoy *Iso.G.5s6M* in 42° 21′.81N., 8° 46′.16W.

NM1465/21

p414 **BAHIA DE CADIZ**, Plan

Delete legend AIS at R port pillar Lt buoy Fl(2)R.9s6M in

36°35′.78N 6°23′.94W

ILNW 19/20

The CRUISING ALMANAC

TIDE TABLES 2021

p5 **PORTLAND** Delete existing page 5 and replace with [this file](#). This link includes additional amendments to the text.

p9 **SOUTHAMPTON** Delete existing page 9 and replace with [this file](#).

ON ALL ODD NUMBERED PAGES:

Amend the date of the end of **Summer Time**, marked by the shaded box, from **Saturday 23rd October to Saturday 30th October**. For an example page go to [this link](#). *Editor*
