

CRUISING ALMANAC 2021

CUMULATIVE CORRECTIONS ISSUE 4.0

Cut-off date 1st December 2020

The Cruising Association, its officers, members, the editor and individual authors make no warranty as to the accuracy or reliability of any information contained in this publication and accept no liability for any loss, injury or damage occasioned to any person acting or refraining from action as a result of the use of such information or any decision made or action taken in reliance or partial reliance on it save that nothing contained in this publication in any way limits or excludes liability for negligence causing death or personal injury or for anything which may not legally be excluded or limited. No national hydrographic office has verified the information in these corrections and none accept liability for the accuracy of reproduction or any modifications made thereafter therefore **this product should not be used for navigation.** **New or amended Notices since the last Issue will be highlighted thus.**

Please report any errors or omissions to almanac@theca.org.uk.

Covid-19

The Covid-19 crisis has prohibited or restricted cruising in many countries. For the latest information please visit:

https://www.theca.org.uk/public/covid_19_cruising_restrictions

General Information

p13 EFFECT OF BREXIT, VAT

Amend the paragraph text for **The UK Approach** by clicking [here](#). CA

p16 **FIRST AID** Col 2, final sentence. **Delete** "This is available as a free download." and substituting "This may be purchased as a hardback or downloadable pdf." Ed

p18 DENMARK

Danmarks Radio 243kHz

Additional time 1145 RE

p19 FRANCE

Amend third table to read:

The Baie de Somme	Antifer	80	0803, 1633, 2003
to Cap de la Hague	Port-en-Bessin	80	0745, 1515, 1945
(Joburg)	Joburg	80	0733, 1603, 1933

Amend last table to read:

Anse de l'Aiguillon	Chassiron	63	Every 20 mins
to the Spanish	Soulac	79	0715, 1545, 1915
Frontier (Etel)	Cap-Ferret	63	Every 20 mins
	Contis	79	0745, 1615, 1945
	Biarritz	79	0803, 1633, 2003

p19 SPAIN

Amend first table to read

Bilbao	10, 74	0433, 0833, 1033, 1833, 2233
		0500, 1100, 1500, 2100
Santander	72	
Gijón	10	0900, 2100
A Coruña	10	0005, 0405, 1605, 2005
Finisterre	11	4-hourly from 0233
Vigo	10	4-hourly from 0015
Cádiz	15	4-hourly from 0315

Tarifa	10	Even hours +0015
Huelva	10	0815, 1215, 2015
Algeciras	74	0515, 1515, 2315

Amend in second table VHF Channel of Tarifa to
Tarifa 83

Replace "0340, 1340, 1903" by 0200, 1115, 1633

England South Coast

p44 **DARTMOUTH**, Text,

Tel/VHF Insert <https://www.dartharbour.org/news-and-notice/port-notice/2020/07/17/Intm-12-2020-temporary-emergency-duty-mobile-number/>

p50 **WEYMOUTH HARBOUR**, Plan

Move special buoy Fl(4)Y.10s, from: 50° 36'·35N., 2° 26'·24W to: 50° 36'·40N., 2° 26'·20W. NM4364/20

p73 **LITTLEHAMPTON** Plan

Insert Light Q.R in 50° 48'·448N., 0° 32'·784W NM5909/20

p77 **DOVER HARBOUR**, Plan

Amend light to, VQ.14m4M 51° 06'·85N., 1° 19'·38E NM5197/20

Insert lights Fl.R.2s in 51° 07'·12N., 1° 19'·36E. and

2F.G (vert) in 51° 07'·10N., 1° 19'·24E. NM5277/20

England East Coast

p92 **RIVERS CROUCH AND ROACH**, Plan

Delete Lit G buoy, **Fairway No 3** in 51° 37'·18N., 0° 49'·91E NM4735/20

Move unlit Y buoy **Raysand**, from: 51° 39'·10N., 0° 59'·50E. to 51° 39'·08N., 0° 59'·28E. NM4836/20

p101 **RIVERS ORE AND ALDE**, Plan
Orfordness lighthouse ruin in 52°05'.00N 1°34.40E, amend legend 'Disused' to 'Demolished'. *Editor 8/2020*

p105 **BLAKENEY HARBOUR**, Plan
Insert
No 3A Stb buoy Fl.G 1s in 52°58'.90., 0° 58'.00E
Amend as follows
No 1 Stb buoy Fl.G.5s in 52° 59'.04 N, 0° 57'.80E
No 2 Stb buoy Fl.(2).G.8s in 52° 59'.03N., 0° 57'.95E
No 3 Stb buoy Fl.G.4s in 52° 58'.98N., 0° 58'.03 E
Local 3/6/20

p106 **WELLS-NEXT-THE-SEA**, Plan
Move W card **Wells Harbour** Q(9)15s to: 52° 59'.68N., 0° 50'.24E.
NM3218/20

p116 **NORTH SUNDERLAND**, Text
Amend Mobile Tel No 0790 4726121 . *HM*

Scotland East and North Coasts

None to date

Scotland West Coast

p146 **KYLE AKIN**, Plan
Move lit R buoy Fl.R.6s, from:
57° 16'.71N., 5° 45'.31W. to: 57° 16'.68N., 5° 45'.20W.
NM4605/20

p150 **CORPACH**, Plan
Insert legend *Marine under construction* between
56° 50'.535N., 5° 07'.462W. and 56° 50'.540N., 5° 07'.627W.
NM3768/20

p151 **CORPACH**, Text
Insert at end of text:
New Marina www.corpachmarina.co.uk/ gives details and photo of new marina construction. *Ed20/08/20*

England West Coast, Wales, & Isle of Man

p177 **MENAI STRAIT NE ENTRANCE**, Plan
Amend Characteristics of **Trwyn Du** light in 53° 18'.77N., 4° 02'.45W to Fl.5s19m9M Horn(1)30s. *NM4948/20*

p189 **SAUNDERSFOOT**, Plan
Replace unlit R buoy with lit Y can buoy Q.Y. in
51° 42'.48N., 4° 41'.38W. *NM5224/20*

p192 **PORTISHEAD**, Plan
Firefly Rocks: Amend depth 0.9 to 1.6 in 51° 29'.90N., 2°45'.49W
Bristol Dock Surv 2020

p193 **WATCHET**, Text
Amend marina *mobile* tel no to 07394 238218 (out of hours) *Ed*

p195 **PADSTOW**, Plan
Insert G buoy Fl.G.10s **Gun Point** in 50° 33'.26N., 4° 56'.24W.
Insert R buoy Fl.R.5s **Brea Beach** in 50° 33'.04N., 4° 56'.03W.
Move R buoy Fl(2)R.5s **Brea Spit**, from:
50° 33'.20N., 4° 56'.08W. to: 50° 33'.30N., 4° 56'.12W. *NM2963/20*
Insert lit R buoy LFl.R.10s **Daymer** in 50° 33'.50N., 4° 56'.12W.
Move lit G buoy Fl.G.5s **Doom Bar** to: 50° 33'.40N., 4° 56'.28W. *NM5626/19*
Insert isolated danger buoy Fl(2)10s in 50° 33'.79N., 4° 56'.14W
Delete isolated danger buoy Fl(2) in 50° 32'.50N., 4° 55'.61W *NM4193/20*

Ireland

p198 &199
Tables CG Radio and Met amends as follows:
CG Radio & Met VHF
Dublin 03
Rosslare 05
Mine Head 03
Cork 02
Bantry 05
Valentia 62
Shannon 64
Belmullet 63
Clifden 03
Malin Head 01,05
Glen Head 03 *IRNM36/20*

p214 **WATERFORD HARBOUR**, Plan
Insert plan **DUNMORE EAST HARBOUR** Amend pierhead light in 52° 08'.98N 6° 59'.37M from Fl.R.10s 6m4M to Fl(3)R.10s 6m4M *NM5113/20*

p217 **DUBLIN BAY**, Plan
Amend light-buoy to, Iso.4s in 53° 19'.91N., 6° 04'.64W. *NM4242/20*

p219 **HOWTH**, Plan
Inert legend *Works in progress2020* in 53°'23'.47N 6°04'.16W *NM5653/20*

Belgium

None to date

Netherlands

p270 **ZEEGBUT VAN TERSCHELLING**, Plan
Amend **ZS 3** light-buoy to, Q.G in 53° 19'.29N., 4° 59'.48E.
ZS 4 light-buoy to, Q.R in 53° 19'.55N., 4° 59'.64E. *NM1977/20*

p271 **AMELAND (NES)**, Text
Insert Very popular in season. Dredged to 1.4m at CD. Contact HM. Small supermarket nearby. VHF31. *Ed*

Approaches to the Baltic

None to date

France, North Coast, and Channel Islands

p324 **ST-VAAST-LA-HOGUE**, Plan

Amend Light, Pointe de Saire, in 49° 36' 38 N

1° 13' 79, to Iso W 4s 11m 10M *Lights List Wk47/20.*

p331 **BEAUCETTE**, plan

Delete radar bn, Racon(P), at light in 49° 30' 83N.,

2° 29' 14W. *NM5309/20*

p336 **ST-MALO APPROACHES**, Plan

Delete Automatic Identification System, AIS, at lights in

48° 40' 20N., 2° 04' 96W.

48° 40' 27N., 1° 58' 69W.

48° 38' 13N., 2° 01' 30W.

48° 37' 57N., 2° 00' 25W. *NM5625/20*

France, West Coast

None to date

Atlantic Spain and Portugal

p393 **AVILES**, Plan

Amend lights as follows:

Punta de la Forcada to Fl(1+2) 14.5s 23m in

43° 35' 83 N, 5° 56' 85 W

Punta del Castillo to Fl.R.5s 12m 5M in

43° 35' 73 N, 5° 56' 74 W *RE*

p388 **PUERTO DE GOSTRO URDIALES** /Text

Insert ☉ Club 942 86 15 85 *RE*

p388 **PUERTO DE LEQUEITIO**, Text

Insert ☉ 688 67 10 11 *RE*

p398 **PUERTO DE BILBAO**, Text

Amend to Tel **Getxo** 944 91 13 54 *RE*

The CRUTSING ALMANAC

TIDAL STREAM 2021

p5 **PORTLAND**,

Delete existing page 5 and replace with [this file](#).

ILNW
