

CRUISING ALMANAC 2024

CUMULATIVE CORRECTIONS ISSUE 4.0

Cut-off date 30th November 2023

The Cruising Association, its officers, members, the editor and individual authors make no warranty as to the accuracy or reliability of any information contained in this publication and accept no liability for any loss, injury or damage occasioned to any person acting or refraining from action as a result of the use of such information or any decision made or action taken in reliance or partial reliance on it save that nothing contained in this publication in any way limits or excludes liability for negligence causing death or personal injury or for anything which may not legally be excluded or limited. No national hydrographic office, or local harbour authority has verified the information in these corrections, and none accept liability for the accuracy of reproduction or any modifications made thereafter therefore **this product should not be used for navigation**. New or amended Notices since the last Issue will be highlighted thus.

Please report any errors or omissions to <u>almanac@theca.org.uk</u>. Free monthly corrections by email are available by signing in at <u>www.theca.org.uk/almanac/corrections</u>.

General Information

none to date

England South Coast

p46/7 **TEIGNMOUTH HARBOUR,** Plan and text **Insert** depth 1.1 in 50° 32′.37N 3° 29′.46W.

NM4180/22

Col 3 Replace There is ... 265° by: There is a dredged channel, (least depth 1.0m) marked by a Ldg line (Lucette Lt Oc.R.6s on the training wall on the left of the entrance with vertical W stripe on the sea wall or two vertical R lights) on 264°/084°. RE

p55 POOLE HARBOUR, Wareham Channel

Col 3 Supplies, Delete Fuel at Corals,.....before br. RE July 2023

p57 YARMOUTH, Text

Entrance; Insert, Line 13. Some of the visitors' buoys N of the breakwater are in shallower water than shown on the chart and in the Harbour Guide. Parts of the western end of the middle trot (9-12m LOA) have only about 0.5m at CD. Deepest water is to the east. If in doubt, call the HM. RE August 2023

p69 LANGSTONE HARBOUR, Plan

Insert Con G buoy LFI.G *Mulberry* in 50° 47′ ·82N., 1° 01′ ·64W. NM3332/23

p75 NEWHAVEN Plan

Amend light at LT HO from Oc(2)10s17m12M to, Iso.4s17m12M in 50° 46′.55N 0° 03′.51E NM882/23

p76 EASTBOURNE – SOVEREIGN HARBOUR, Plan Delete G buoy Fl.G.3s in 50° 47´·37N 0° 20´·21E. NM659/23

p77 DOVER HARBOUR, Plan

Delete pier-head light Fl(2)R.5s in 51° 07´.50 N 1° 20´.28 E. NM1085/23

England East Coast

p88 RIVER THAMES, Tex, Col 4 Line 20,

Limehouse Dock Marina Replace text " No visitors with" :

Visitor berths are usually available. Contact the marina office 0207 308 9930 well before arrival, when you reach Limehouse call again on VHF 80. Berthing normally on pontoon H, max draft 2m. This is the headquarters of the CA, with its club house, library overlooks the basin and welcomes visitors. Ed

p 96 WALTON BACKWATERS, Text

Col4, line5: Replace "Channel on plan." with " After about 1M, at the unlit N card buoy, the deep water channel curves to the West and Titchmarsh Marina. Or to the South, at HW -0300, for draft 1.6m, a narrow buoyed channel leads to WFYC where a quay can be used HW -0200 to HW. " Ed

p 97 WALTON BACKWATERS, Inset Plan

Insert N Card buoy (unlit) in 51° 51'-85 N 1° 16'-20 E. Ed

p102 **ORFORD HAVEN,** Text Col2 **Facilities** line 4: Delete "Orford garage (½M) or" Ed

p103 **LOWESTOFT**, Text

Col 1 line 4 Insert Two white, lit, rectangular marks have been built in 52°27'·64N 1°44'·61E Fl.Y 5s and In 52°27'·72N 1°45'·82E Fl.Y 2·5s HM .

p103 LOWESTOFT, TEMPORARY NOTICE

GUL WING BRIDGE will be closed to all shipping for a period of THREE weeks from 24th January 2024 Works in progress.

East and North Scotland Coasts

p119 BERWICK TO ARBROTH, Passage Lights Isle of May , amend Range from 22M to 18M. NL09

p123 RIVER TAY Continuation, Plan

Insert E card buoy VQ(3)5s in 56° 27′.60N 2° 57′.16W and delete legend 2Bns close W of above NM247/23

p125 PETERHEAD Plan

Replace depth 2·4, with depth 1·6, and extend 2m contour E to enclose in 57° $30' \cdot 51N$ 1° $46' \cdot 24W$. NM3443/22

p127 **BUCKIE,** Plan **Amend** light to, Fl.G.2s5m4M in 57° 40′ ·81N 2° 57′ ·65W. NM3732/23

p128 **BURGHEAD,** Plan

 Amend range of light to 2M, in 57° 42′·11N

 3° 29′·93W and range of light to 3M, in 57° 42′·08N

 3° 30′·03W.
 NM4582/23

p135 SHETLAND, Plan

Fair Isle: North Skroo light in 59° 33´·13N 1°36°·59W,amend Range from 22M to 18M .NL 14/22

Scotland West Coast

p**157 STORNOWAY,** Plan

Delete depth 6·8m and surrounding dotted circle in 58° 11′·86N 6° 22′·80W. NM4143/23

p161 CAMBLETOWN, Plan

Insert depth: 0.8m in 55°25'.88N 5°33'.60W and extend 2m depth to enclose. ILNW 177/22

England West Coast and Wales

p180 HOLYHEAD, Plan

Amend fog signal Siren(1)20s to Horn(1)20s at Lt in 53°19'·85N 4°37'·16W ILNW 231/23

p183 FISHGUARD, Text

 Tel/VHF Old Harbour. Amend HM 01348 873389 to

 HM office 01834 842717.
 RE

p188 NAVIGATION IN THE BRISTOL CHANNEL

Nash Point Amend range, white to 19M and red to14MTH41/22Trevose Head Amend range to 18MAd Lt List 10/23

p195 **PADSTOW,** Plan

Move G lighted buoy FI.G.5s *Doom Bar* from 50° 33'·59 N 4° 56'·23 W to 50° 33'·51N 4° 56'·31 W **Move** R lighted buoy LFI.R.10s *Daymer* from 50° 33'·50 N 4° 56'· 39 W to 50° 33'·49N 4° 56'·20 W **Move** G lighted buoy FI.G.10s *Gun Pt* from 50° 33'·26N 4° 56'·24 W to 50° 33'·27 N 4° 56.25 W **Insert** Wreck buoy symbol It FI(2).G.5s *Antoinette* in 50° 33'·81 N 4° 56'·17' W and **Delete** existing wreck buoy FI(2).10s close SW. ILNW11/2023

Ireland

p201 VALENTIA, Plan

Insert W card buoy YBY Q(9)15s in 51° 56′.71N 10° 17′.49W and delete isolated danger mark Fl(2)6s close by. NM2649/23

p212 CORK TO TUSKAR ROCK, Passage Lights Tuskar Rock

Amend range of Lt Q(2)7.5s33m24M to 18M

ILNW 384/22

p215 WATERFORD, Text Waterford City Marina will be closed to visitor until 2025. Works in progress. City Council

p218 DUBLIN BAY, Plan

Move No 1 G con buoy to 53° 20´·27N 6° 05´·26W NM3016/23

p219 HOWTH, Plan

Amend light to, 2F.R(vert)3M7m in 53° 23´·50N 6° 04´·08W. NM3625/23

p223 BELFAST, Plan

Amend light to, Fl.Y jn 54° 36′·34N 5° 54′·90W. Delete pier light 2F.G (vert) in 54° 36′·27N 5° 55′·18W NM1906/2023

p231BURTONPORT, Text

Col 1 line 7. After 081487 6482 insert or 0873 354831, main office 0868 310121. Ed 9/23

p240 **CASHLA BAY,** Plan Insert depth 0.8 m in 53° 16′.50N., 9° 33′.87W and extend 2m contour SW to enclose . NM3589/23

p241 KILRONAN HARBOUR, Text Anchorage Insert: Easy access; keep clear of ferries.Ed

Belgium

none to date

Netherlands

p255 STANDING MAST ROUTE , Text

Col 1, line 4: **INSERT** "local time" after "0200". Col 1, At end of 1st paragraph insert "Amsterdam rail bridge not operating from 1st Oct 2023 until 31st May 2024 for vessels with more than 6.25 m above normal canal level. Use the Haarlem route instead."

p257 APPROACHES TO THE WESTERSCHELDE, Plan

Insert R can Lt buoy SS 2 Q.R in 51°25'.50N 3°37'.92E. Delete R spar buoy SS 2 close to NW Replace G starboard spar buoy SS 5 with Y special pillar buoy ARV 5 in 51°24'.71 N 3°38'.04E Delete G starboard spar buoy SS 3 in 51°25'.04N 3°37'.30E. Delete R can Lt buoy SS 4 Q.R in 51°25'.23N 3°37'.82E ILNW 304/22

p259 ENTRANCE TO THE OOTTERSCHELDE, Plan

 Replace lit bn LFI.R.8s WG 4 with unlit bn OS 11 in

 51° 38´.62N
 3° 28´.82E
 NM4975/22

Approaches to the Baltic

p304 LAGUNEN YACHT HARBOUR, Plan Latitude scale. Insert 12° before 56´·0 RE11/2023

p306 WARNEMUNDE Plan

Insert E card buoy, BYB, in 54° 11′.05N 12° 05′.26E.' NM2971/23

France North Coast, and Channel Islands

p316 **DUNKERQUE,** Plan **Move** G con buoy Q.G *DW29* to 51° 03´.81N 2°20´.20E. NM3541/23

p320 **ST-VALERY-EN-CAUZ,** Plan **Amend** height of stb pierhead light from 13m to 12m. NMWk43Lt List

p321 **FECAMP**, Plan **Amend** light to Fl(2) 6s 15m 12M at Jetée Nord, Head in 49° 45′·92 N 0° 21′·80 E NM 4692/23

p329 PASSAGE LIGHTS, Guernsey
Plate Fougere Delete Racon (P)
ILNW

p338 **ST MALO APPROACHES,** Plan **Insert** rock which covers / uncovers sym. in 48°39'·48N 2°01'·71W ILNW204/23 **Delete** unlit R buoy with top mark No4 Bell in 48° 40'·24N 2° 07'·20W NM4444/23

p341RIVER RANCE, Text

Col 1: Plouër Marina. Amend "10 visitors' berths" to "visitors usually berth on B pontoon, best to call HM". Delete "two waiting pontoons outside marina". Ed

p341 ST-CAST-LE-GUIDO, Text

Col 2: Approach At end, insert "there are numerous fishing floats in the approaches, extreme caution advised at night." Ed

p341 **ST CAST**, Plan, Longitude Scale. **Amend** 15.5' to 14'·5 . Ed

p345 **RIVIERE DE TREGUIER,** Plan Delete fog signal, *Whis*, at light-buoy, Basse Crublent, in 48° 54′·28N 3° 11′·15W. NM3951/23

France, West Coast

p366 CONCARNEAU, Text
Facilities Insert Fuel RE

p378 **LES SABLES D'OLONNE,** Plan **Insert** sectors at light, Iso.4s33m16M in: 46° 29'.58N., 1° 46'.23W as follows W 25°- 40° (15°) NM4008/23

Northwest Spain

p388 **HONDARRIBIA AND HENAYE,** Plan Insert Y special spar buoy in 43°22'·02N 1°47'·05W ILNW 43/23

p394 PUERTO DE RIBADESELLA

The depth to the NW of the marina is no longer maintained. Delete lgd 1·5m centred on 43°27'·89N 5°03'·75W ILNW 19/23

Portugal, Southwest Spain, and Gibraltar p416 PORTIMAO Plan

Delete anchorage sym in 37°07'·75N 8°31'·63W ILNW 170/23

p417 **VILAMOURA,** Plan Amend range of Lt Fl.5s17m19M to 12M in 37°04′·47N 8°07′·38W ILNW 26/23
