



CRUISING ALMANAC 2022

CUMULATIVE CORRECTIONS ISSUE 5.0

Cut-off date 4th January 2022

The Cruising Association, its officers, members, the editor and individual authors make no warranty as to the accuracy or reliability of any information contained in this publication and accept no liability for any loss, injury or damage occasioned to any person acting or refraining from action as a result of the use of such information or any decision made or action taken in reliance or partial reliance on it save that nothing contained in this publication in any way limits or excludes liability for negligence causing death or personal injury or for anything which may not legally be excluded or limited. No national hydrographic office, or local harbour authority has verified the information in these corrections, and none accept liability for the accuracy of reproduction or any modifications made thereafter therefore **this product should not be used for navigation**. New or amended Notices since the last Issue will be highlighted thus. Please report any errors or omissions to almanac@theca.org.uk.

Covid-19

The Covid-19 crisis has prohibited or restricted cruising in many countries. For the latest information please visit: https://www.theca.org.uk/public/covid_19_cruising_restrictions

General Information

p10 COASTGUARD OPERATION CENTRES

Norway. Delete first two lines, Stations Rogaland and Tjøme. Replace with:

Norwegian Coastal Radio South MMSI 002570000
Telephone +47 51517000/+47120 RE No21

p18 APPROACHES TO THE BALTIC

Norway Coastal Radio Stations delete sentence "No prior call" (there is an announcement on VHF 16 before weather forecast on working ch).

Insert:

Warnings on MF.....and Rogaland Ch 260 (1692kHz) – rather than (1682kHz) RE No21

England South Coast

p24 ENGLAND SOUTH COAST, Upper Plan

Delete "Channel" with light vessel symbol in 49° 54'·46N 2° 53'·74W and Insert RW vertical stripe buoy with R spherical topmark. TH12/2021

p27 ISLES OF SCILLY St Mary's

Insert unlit Special buoy in 49° 54'·70N 6° 18'·90W. NM2131/21

p31 ST MICHAEL'S MOUNT/ MARAZION, Plan

Amend background colour of 2M depth to a pale colour in 50° 06'·98N 5° 28'·98W RE

p35 FOWEY, Plan

Insert drying height, 0, and extend 0m low water line N to enclose 50° 19'·793N., 4° 38'·127W. NM5319/21

p37 PLYMOUYH SOUND, Plan

Delete legend "Bovisand Pier" in 50° 20'·3 N 4° 50'·3 W. RE

p37 PLYMOUTH SOUND, Plan

Amend light to, Fl.WR.10s19m12/9M Horn(1)15s in 50° 20'·07N 4° 09'·52W. NM4424/21

p38 MILLBAY, Plan

Insert legend, "Small Craft Anchorage" in 50° 21'·77N 4° 08'·77 W. RE

p38 MILLBAY, Text

col 1: Anchorage
Delete text "No longer sea bed". RE

p39 HAMOAZE, Plan

Amend "Sound Acre Pt" to "Sandacre Pt" in 50° 23'·6 N 4° 13'·5 W. RE

p40 **Text** Col 1

Delete the five lines "Navigation charts." RE

p48 **RIVER EXE**, Plan

Insert G buoy, named Hinton, Fl(2)G5s in
50° 36'·99 N 3° 26'·29 W. ExeterNM19/21

Move No21 G buoy to 50° 37'·85N 3°26'·39W
ExeterNM24/21

p 50 **PORTLAND HARBOUR**, Plan

Delete legend, SS(Traffic), at light in 50° 34'·45N.,
2° 27'·25W. NM3785/21

Move YC symbol and legend 'Castle Cove SC' from
50° 35'·83N 2° 27'·56W to 50° 35'·59N 2° 27'·90W
RE

p54 **POOLE TO CHICHESTER**, Passage Lights

Amend Saint Catherine's Point light to, Fl.5s41m18M
& F.R.35m13M NM4234/21

p60 **BEAULIEU RIVER**, Plan

Bucklers Hard Yacht Harbour: **Amend** light
characteristics at each end of outer pontoon H from
2.F.Y(vert) to 2.F.R(vert) in 50° 48'·16N 1° 25'·26W
and 50° 48'·20N 1° 25'·18W NM4860/21

Text, Facilities **Insert** Pump-Out Harbour

p65 **RIVER HAMBLE**, Plan and Insets

[Click here](#) for revised Plan which shows the following
changes:

Deacons Marina: Delete isolated pontoons and insert
pontoons connected to the shore as shown on new
plan.

Swanwick Marina: Amend lettering of pontoons and
move fuel berth to NW pontoon as shown. ILNW/CA

p77 **DOVER MARINA**, Plan

Insert symbol with legend SS(Traffic)
in 51° 07'·197N., 1° 18'·709E. NM3934/21

England East Coast

p81 **North Foreland to Harwich**

Replace Sunk Centre LtV with
Sunk Centre Pillar Buoy
Mo.(A)15s Racon C (-···) AIS TH15/2021

p83 **THAMES ESTUARY PASSAGE**, Plan

Insert Y special pillar Lt buoy Fl.Y.5s in
51°19'·82N 1°40'·28E ILNW 593/20

Amend fog signal on **S Knock** light buoy to Bell in 51°
34'·14N 1° 34'·29E. NM2229/21

Replace Sunk Centre Light vessel with a Lt pillar buoy
R and W vertical stripes with R spherical topmark
Mo.(A)15s AIS in 51° 50'·10N 1° 46'·02E.
TH15/2021

Amend fog signal on **N Shipwash** light buoy to Bell in
52° 01'·73N 1° 38'·23'E. TH22/2021

p88 **RIVER THAMES** Text

Col 4. **Delete Gallions Point Marina** and associated
text. East Coast Pilot Nov/21

p90 **RIVER THAMES**, Plans

Upper Plan. **Delete** Inset plan **Gallions Point Marina**.
Lower Plan. **Delete** legend Gallions Pont Marina,
associated text and Yacht Berthing symbol in
51° 31'·0N 0° 04'·0E, East Coast Pilot Nov/21

p91 **RIVER CROUCH, COLNE, AND BLACKWATER**
APPROCHES

Swallow Tail

Move:

Y special purpose pillar Lt buoy Swallowtail No 1
from 51°41'·39N 1°08'·21E to 51°41'·40N 1° 07'·50E

Delete Y special purpose pillar Lt buoy Swallowtail
No 2 in 51°41'·18N 1°06'·30E

Rename:

Y special purpose pillar Lt buoys:
Swallowtail No 3 to Swallowtail No 2 in 51°40'·84N
1°04'·39E. The Lt has been amended to Fl. Y.10s.
Swallowtail No 4 to Swallowtail No 3 in 51°40'·52N
1°03'·49E. The Lt remains Fl(2)Y.10s ILNW 292/21

Whitaker

Move:

Whitaker No 1 G con buoy to 51°40'·53N 1°05'·40E
Whitaker No 2 R can buoy to 51°40'·25N 1°05'·40E

Delete:

Whitaker No 3 G con buoy in 51°40'·40N 1°04'·74E
Whitaker No 4 R can buoy in 51°40'·16N 1°04'·91E

Rename and Amend Lts:

Whitaker No 5 G con buoy to Whitaker No 3 in
51°40'·04N 1°03'·22E. Amend Lt to Fl(2)G.5s
Whitaker No 6 R can buoy to Whitaker No 4 in
51° 39'·76N 1° 03'·48E. Amend Lt to Fl(2)R.5s
Whitaker No 7 G con buoy to Whitaker No 5 in
51°39'·54N 1°02'·00E. Amend Lt to Fl(3)G.10s
Whitaker No 8 R can buoy to Whitaker No 6 in
51°39'·35N 1°02'·00E. Amend Lt to Fl(3)R.10s

ILNW 315/21

Click [Here](#) for a revised Plan which includes the corrections for the **Swallow Tail and Whitaker buoys** shown above.

Insert Y special buoy with X top mark Fl(5)Y in 51° 39'·83N 1° 01'·56E. NM/4038

p92 **RIVERS CROUCH AND ROACH**, Plan

Delete Lit G buoy, **Fairway No 3** in 51° 37'·18N 0° 09'·91E. NM4735/20

Move unlit Y buoy **Raysand**, from: 51° 39'·10N 0° 59'·50E to 51° 39'·08N 0° 59'·28E. NM4836/20

Delete R can buoy **Fairway No 2** in 51° 37'·27N 0° 48'·84E. NM2655/21

Bridgemarsh Marina Approach, Plan

Insert Lt R bn Fl.R.5·5s in 51° 38'·43N 0° 45'·80E and delete existing Lt R bn Fl.R.10s, close SW of the above. NM3261/21

p94 **RIVER BLACKWATER**, Plan

Heybridge Basin Insert G con buoy Fl.G.2s in 51° 43'·647N 0° 42'·651E.

Maldon approach Insert G con buoy Fl.G.3s No 17 in (a) 51° 43'·658N 0° 41'·771E. Delete former G channel buoy No 17, close NW of: (a) above. NM5002/21

p99 **HARWICH AND FELIXSTOWE**, Text **Halfpenny Pier**, Insert 'Open April to October' HHA 32/2021

p103 **LOWESTOFT**, Text

Entrance Before "Access to the broads" Insert "Construction work on the Gull Wing bridge is under construction. During construction a navigational channel will be maintained. For the latest information contact ABP Lowestoft" ILNW 112/21

p103 **LOWESTOFT**, Upper Plan

Insert below the heading **LOWESTOFT** " Lifting Bridge under const'n " centred on 52°28'·44N 1°44'·22E ILNW 112/21

Insert a dotted line across Lake Lothing in direction 010° - 190° centred on 52°28'·44N 1°44'·22E with legend "approx position of future new bridge" Editor

p105 **BLAKENEY HARBOUR**, Plans

Move unlit RW buoy **Fairway** to 52° 59'·17N 0° 58'·48E Local NM

p107 **APPROACHES TO KING'S LYNN AND WISBECH**

Outer Westmark Knock. Move:
BYB E card Lt buoy **East Knock** from 52°52'·14N 0°14'·69E to 52°52'·15N 0°12'·10E
YB S card Lt buoy **Lake** from 52°51'·00N 0°13'·52E to 52°51'·00N 0°13'·00E
BYB E card Lt buoy **MAC** from 52°50'·59N 0°12'·47E to 52°50'·65N 0°12'·99E ILNW 408/21

p116 **FARNE ISLANDS**, Plan

Insert drying patch centred on 55°38'·63N 1°37'·03W ILNW 327/21

Farne Island Inner Lt Ho On or about 2nd March 2020
Change characteristics from Fl(2)WR.15m 27m10/17M to Fl(2)WR.15m 27m8/8M TH26/2021

Scotland East and North Coasts

p119 **EYEMOUTH**, Plan

Insert Rock depth 2.5m enclosed by dangerline in 55°52'·73N 2°05'·49W

Replace rock depth 1.2m with 0.3m in 55°52'·76N 2°05'·22W ILNW 261/21

p120 **DUNBAR**, Text

Approach At end insert ". There is only 75m between drying rocks Scart and Castlefoot "

Facilities Insert "Water on the pier". Ed

p124 **ARBROATH**, Text

Introduction Amend "contact HM for accurate times." to "contact HM before arrival".

Entrance and Berthing At end insert "Waiting pontoon in outer harbour, dries to soft mud." Ed

p125 **ABERDEEN**, Plan

Draw dotted line between 57° 08'·28N 2° 02'·84W. 57° 08'·28N 2° 02'·15W. with legend 'New harbour under construction to the south of this line to 57° 07'·75N 2021/2022.' NM5056(P)/21

p130 **WICK**, Plan

Insert depth 2·1 in 58° 26'·33N 3° 04'·81W. NM0115/22

p132 **STROMNESS**, Plan

Amend light to, Fl.4s7m7M in 58° 56'·95N 3° 17'·83W. NM3462/21

p133 **SCAPA FLOW**, Plan

Amend light to, Fl.4s7m7M in 58° 56'·95N 3° 17'·83W. NM3462/21

Rock depth 2.5m enclosed by dangerline in 55°52'·73N 2°05'·49W Replace rock depth 1.2m with 0.3m in 55°52'·76N 2°05'·22W (ILNW 261/21)

Scotland West Coast

p157 **STORNAWAY HARBOUR**, Plan
Amend light to Dir.WRG.4s23m5M in 58° 12'·00N
6° 23'·54W. NM3002/2

p164 **ARDROSSAN**, Text
Col 1 Lines 19 to 22. Amend to:
•3 F.R.(vert). Hbr and Marina closed to all traffic.
Clyde Marina

England West Coast, Wales, & Isle of Man

p171 **MARYPORT HARBOUR**, Plan
Insert shore pier lights
Fl.R.3s in 54° 43'·05N 3° 30'·46W.
Fl.R.5s in 54° 42'·98N 3° 30'·20W.
Fl.G.5s in 54° 42'·94N 3° 30'·25W.
Replace Old Lt Ho and symbol with shore pier Lt
Fl.G.3s in 54° 43'·02N 3° 30'·46W. NM3674/21

p177 **MENAI STRAIT NE ENTRANCE**, Plan
Delete pierhead light Fl.R.3s in 53°14'·44N 4°07'·57W
NM4799/21

p183 **FISHGUARD**, Text
Tel/VHF Old Harbour. Amend HM 01348 873389 to
HM 01834 842717. Insert at end "assistant HM
07812 559483". RE

p195 **PADSTOW**, Plan
Insert R buoy Fl(2)R 10s **Greenaway** in 50° 33'·79 N
4° 56'·10 E
Delete legend **Greenaway** and **amend** light
characteristic to Fl(2)10s at BRB Isolated Danger Buoy
in 50°33'·79N 4°56'·20W ILNW 411/20

p196 **PADSTOW**, Text
Entrance. col 1: After "and pass Greenaway close to
port." **Insert** " Leave the isolated danger buoy
(marking a wreck) to stb." RE

Ireland

p202 **DARRYNANE**, Plan
Insert Light Bn Fl.G in 51° 45'·64 N 10° 09'·31 W
Light Fl.G 3s to bn in 51° 45'·75 N 10° 09'·16 W
Amend light from 2Fl.R to Fl.R 3s at bn in
51° 45'·76 N 10° 09'·25 W NMWk46SecV

p204 **CASTLETOWN and BEARHAVEN**, Plan
Insert jetty, double firm line, joining:
51° 38'·775N 9° 54'·309W.
51° 38'·734N 9° 54'·322W.
51° 38'·730N 9° 54'·469W.
Insert light Fl.G.5s 6m4M at W end of above jetty.
Delete G buoy Fl.G.5s No 3 in
51° 38'·796N., 9° 54'·430W NM0137/22

p215 **KILMORE QUAY**, Plan
Insert depth, 0₆, and extend 2.0m danger line SE to
enclose in 52° 09'·86N 6° 34'·48W. NM3790/21

p221 **STRANGFORD LOUGH**, Plan
Insert special Lt buoy Fl.Y.10s in 54° 23'·12N
5° 33'·78W. NM0033/22

p225 **FAIR HEAD TO BLOODY FORELAND**
Passage lights
Amend range of the following:
Altacarry Head (Rathlin East) from 26M to 18M.
Rathlin West from 22M to 18M. NM2748/21

p230 **ARRANMORE**, Plan
Insert G con buoy with topmank Fl.G.3s *Torban Buoy*
in 54° 59'·36N 8° 28'·48W. NM5326/21

Belgium

p245 **OOSTENDE**, Plan
Amend Lt to F.G.19m11M in 51° 14'·44N 3° 14'·97E.
Insert fog signal, Horn Mo(U), at the above light

Netherlands

p256 **ENTRANCE TO THE WESTERSCHELDE**, Plan
Insert lit N Card buoy **DAM** in 51° 23'·28N., 3° 35'·97E.
NM5097/21

p257 **HANSWEERT**, Plan
Amend Lt to Oc.4s11m in 51° 27'·18N 3° 59'·42E.
NM5241/21

p262 **APPROACHES TO THE MAAS**, Plan
Move Lt G buoy LFl.G.5s **Maas 1**, from 51° 59'·38N
4° 01'·67E to 51° 59'·36N 4° 01'·90E. NM3246/21

p263 **IJMUIDEN**, Plan
Insert shore lights Iso.6s in 52° 27'·88N 4° 36'·19E
and in 52° 27'·88N 4° 36'·22E. NM5431/21

Approaches to the Baltic

p289 Passage lights

Utsira Amend to FFI (3) 30s 10M RE Nov21

p289 BERGEN, Text

Approaches Amend last two lines to: "Enter Vågen between G buoy and F R Lt on mole head"

RE Nov21

p291 TANANGER, Text

Facilities Delete "Diesel hotel" Insert "Fuel no longer available" HM Nov21

France, North Coast, and Channel Islands

p312 FRANCE NORTH COAST,

Plan Replace symbol of a Lt Vessel by a symbol of a RW vert stripe buoy with R special top mark in 49° 54'·46N 2° 53'·74W. NM3791/21

p320 HONFLEUR, Plan

Amend light at head of Jetée Est from Fl.R to Fl.R 4s in 49° 25'·40N 0° 14'·10 E BA Its list51/21

p321 DIVES-SUR-MER, Text

Insert at end of ENTRACE "Shallow patch of -3.7m at CD reported at the entrance to the marina."

Reg Ed

p321 OUISTREHAM AND CAEN, Plan

Amend light to, Dir Oc(3)R.12s30m18M in 49° 16'·78N 0° 14'·84W.
light to, Dir Oc(3)R.12s11m17M in 49° 17'·10N 0° 14'·80W.
Apply above correction to inset plan NM4867/21

p335 CARTERET,

Insert lights, Fl(3)R.12s2M in 49° 22'·59N., 1° 47'·24W. and Fl(3)G.12s2M in 49° 22'·55N., 1° 47'·20W. NM3743/21

p350 ILE DE BATZ, Plan

Delete W card buoy Notre Dame in 48° 43'·70N., 3° 59'·07W. NM3750/21

France, West Coast

p361 AUDIERNE, Plan

Amend Pierhead light to Fl(2)R.6s in 48° 00'·99N 4° 32'·15W. NM3516/21
Amend Coz Fornic light to Fl.R.4s in 48° 00'·89N 4° 32'·31W. NM3516/21

p376 LES SABLES D'OLONNE, Plan

Delete symbol AIS at Lt Q.33m12M in 46° 29'·62N 1° 47'·79W and insert light flash to the symbol for a shore light. NM5032/21

p375 SAINT-GILLES-CROIX-DE-VIE, Plan

Delete AIS, at light in 46° 41'·96N 1° 56'·61W. NM0038/22

Atlantic Spain and Portugal

p389 PUERTO DE BILBAO, Plan

Delete pierhead Lt Fl.Y.3s in 43° 21'·02N 3° 03'·70W. NM5001/21

p414 BAHIA DE CADIZ, Plan

Insert characteristics Dir F. WRG6s14M to the shore light in 36° 35'·85 N 6° 13'·20 W NM4402/21

p415 CADIZ AND CADIZ BAY, Text

Puerto Santa Maria line 2
Delete: "Ldg Lts Iso..... from"
Insert: "Dir F. WRG6s14M " NM4402/21