



# CRUISING ALMANAC 2024

## CUMULATIVE CORRECTIONS ISSUE 1.0

Cut-off date 12th September 2023

The Cruising Association, its officers, members, the editor and individual authors make no warranty as to the accuracy or reliability of any information contained in this publication and accept no liability for any loss, injury or damage occasioned to any person acting or refraining from action as a result of the use of such information or any decision made or action taken in reliance or partial reliance on it save that nothing contained in this publication in any way limits or excludes liability for negligence causing death or personal injury or for anything which may not legally be excluded or limited. No national hydrographic office, or local harbour authority has verified the information in these corrections, and none accept liability for the accuracy of reproduction or any modifications made thereafter therefore **this product should not be used for navigation**. New or amended Notices since the last Issue will be highlighted thus.

Please report any errors or omissions to [almanac@theca.org.uk](mailto:almanac@theca.org.uk). Free monthly corrections by email are available by signing in at [www.theca.org.uk/almanac/corrections](http://www.theca.org.uk/almanac/corrections).

### General Information

none to date

### England South Coast

p46/7 **TEIGNMOUTH HARBOUR**, Plan and text  
**Insert** depth 1.1 in 50° 32'·37N 3° 29'·46W.

NM4180/22

**Col 3 Replace** There is ... 265° by:

There is a dredged channel, (least depth 1.0m) marked by a Ldg line (Lucette Lt Oc.R.6s on the training wall on the left of the entrance with vertical W stripe on the sea wall or two vertical R lights) on 264°/084°.

RE

p55 **POOLE HARBOUR, Wareham Channel**

**Col 3 Supplies, Delete** Fuel at Corals,.....before br.

RE July 2023

p57 **YARMOUTH**, Text

**Entrance; Insert, Line 13.** Some of the visitors' buoys N of the breakwater are in shallower water than shown on the chart and in the Harbour Guide. Parts of the western end of the middle trot (9-12m LOA) have only about 0.5m at CD. Deepest water is to the east. If in doubt, call the HM.

RE August 2023

p75 **NEWHAVEN** Plan

Amend light at LT HO from Oc(2)10s17m12M to, Iso.4s17m12M in 50° 46'·55N 0° 03'·51E NM882/23

p76 **EASTBOURNE – SOVEREIGN HARBOUR**, Plan

**Delete** G buoy Fl.G.3s in 50° 47'·37N 0° 20'·21E.

NM659/23

p77 **DOVER HARBOUR**, Plan

Delete pier head light Fl(2)R.5s in 51° 07'·50 N

1° 20'·28 E.

NM1085/23

### England East Coast

p88 **RIVER THAMES**, Text

**Limehouse Dock Marina** Replace text " No visitors . . . . with" :

Visitor berths are usually available. Contact the marina office 0207 308 9930 well before arrival, when you reach Limehouse call again on VHF 80. ~~You~~ are Berthing normally on pontoon H, max draft 2m. This is the headquarters of the CA, with its club house, library overlooks the basin and welcomes visitors. Ed

## East and North Scotland Coasts

p119 **BERWICK TO ARBROTH**, *Passage Lights*  
**Isle of May**, amend Range from 22M to 18M. NL09

p123 **RIVER TAY** Cont  
**Insert** E card buoy VQ(3)5s in 56° 27'·60N  
2° 57'·16W and delete legend 2Bns close W of above  
NM247/23

p125 **PETERHEAD** Plan  
**Replace** depth 2·4, with depth 1·6, and extend 2m  
contour E to enclose in 57° 30'·51N 1° 46'·24W.  
NM3443/22

p135 **SHETLAND**, Plan  
**Fair Isle:** North Skroo light in 59° 33'·13N 1°36'·59W,  
amend Range from 22M to 18M. NL 14/22

## England West Coast and Wales

p183 **FISHGUARD**, Text  
**Tel/VHF** Old Harbour. Amend HM 01348 873389 to  
HM office 01834 842717. RE

p188 **NAVIGATION IN THE BRISTOL CHANNEL**  
**Nash Point** Amend range, white to 19M and red to  
14M TH41/22

## Ireland

p201 **VALENTIA**, Plan  
**Insert** W card buoy YBY Q(9)15s in 51° 56'·717N 10°  
17'·49W and delete BRB pillar Fl(2)6s close to E  
NM2649/23

p217 **DUBLIN BAY**, Plan  
**Move** No 1 G con buoy to 53° 20'·27N 6° 05'·26W  
NM3016/23

p223 **BELFAST**, Plan  
Amend light to, Fl.Y jn 54° 36'·34N 5° 54'·90W.  
Delete pier light 2F.G (vert) in 54° 36'·27N 5° 55'·18W  
NM1906/2023

p231 **BURTONPORT**, Text  
Col 1 line 7. After 081487 6482 insert or 0873  
354831, main office 0868 310121. Ed 9/23

p241 **KILRONAN HARBOUR**, Text  
**Anchorage** Insert: Easy access; keep clear of ferries.Ed

## Belgium

none to date

## Netherlands

p257 **APPROACHES TO THE WESTERSCHELDE**, Plan  
**Insert** R can Lt buoy SS 2 Q.R in 51°25'·50N 3°37'·92E.  
**Delete** R spar buoy SS 2 close to NW Replace G  
starboard spar buoy SS 5 with Y special pillar buoy  
ARV 5 in 51°24'·71 N 3°38'·04E  
**Delete** G starboard spar buoy SS 3 in 51°25'·04N  
3°37'·30E.  
**Delete** R can Lt buoy SS 4 Q.R in 51°25'·23N 3°37'·82E  
ILNW 304/22

p259 **ENTRANCE TO THE OOTTERSCHDELDE**, Plan  
**Replace** lit bn LFl.R.8s WG 4 with unlit bn OS 11 in  
51° 38'·62N 3° 28'·82E NM4975/22

## Approaches to the Baltic

p306 **WARNEMUNDE** Plan  
**Insert** E card buoy, BYB, in 54° 11'·05N 12° 05'·26E.  
NM2971/23

## France North Coast, and Channel Islands

p341 **RIVER RANCE**, Text  
**Col 1:** Plouër Marina Amend "10 visitors' berths" to  
"visitors usually berth on B pontoon, best to call HM".  
Delete "two waiting pontoons outside marina". Ed

p341 **ST-CAST-LE-GUIDO**, Text  
**Col 2: Approach** At end, insert "there are numerous  
fishing floats in the approaches extreme caution  
advised at night". Ed

## France, West Coast

p366 **CONCARNEAU**, Text  
**Facilities** Insert Fuel RE

## Spain, Portugal and Gibraltar

none to date **END**